

April 20, 1984

Ms. Betti Harris State Program Section Waste Management Program U.S. EPA Region VII 324 E. Eleventh St. Kansas City, MO 64106

Marc- Pls pull This gile + Letermine ig they stored over 90 Saip + let 5 me know. MBR Sh

APR 25 1984

EPA-ARWM/WMBR

Region VII K.C., MO

Dear Ms. Harris:

Attached hereto is a copy of a letter from Armco, Inc. concerning the reclassification of their Union Wire Rope facility (MODO01686740) to generator status only. It is stated in this letter that Union Wire Rope has never acted as a TSD facility. If this is true, then they may be removed administratively. If EPA has evidence indicating that the Union Wire Rope facility has stored hazardous waste for over 90 days, then notify me and MDNR will begin closure plan review in accordance with 40 CFR 265.112(d).

I believe the compliance branch of your agency has had involvement with this facility, so you may wish to contact Mr. David Doyle concerning this status change.

If there are any questions, please advise.

Sincerely,

Paul Meiburger

Environmental Engineer Waste Management Program

PM/bki

Attachment

cc: Leland Scott David Doyle

R00065079

RCRA Records Center

Christopher S. Bond Governor Fred A. Lafser Director

Division of Environmental Quality Robert J. Schreiber Jr., P.E. Director

11SSOURI DEPARTMENT OF NATURAL RESOURCES



ARMCO MIDWESTERN STEEL DIVISION

April 10, 1984



Mr. Arthur H. Groner Chief, Enforcement Unit Waste Management Program Missouri Department of Natural Resources 1915 Southridge Drive Jefferson City, MO 65102

APR 13 1984

WASTE MANAGEMENT PROGRAM

Dear Mr. Groner:

In response to your March 12, 1984 letter requesting a closure plan, closure cost estimate, and financial assurance mechanism for our Union Wire Rope facility, I have enclosed an updated closure plan and closure cost estimate.

In 1980, a Part A Permit Application was submitted to EPA for our Union Wire Rope facility. The application included notification as both a generator and T/S/D facility for waste pickle liquor (K062) and paint residues (F017). Since that time paint residues have been delisted and in any case we no longer generate them.

In our pickling operation we continually regenerate our acid and sell ferrous sulphate crystals from the regeneration process. We do not store nor have we stored over 90 days any pickle liquor. We will not be storing any pickle liquor over 90 days in the future and request that Union Wire Rope be returned to generator only status. For this reason we have not included the financial assurance required by the State pending your response to this request.

We would appreciate your assistance in the steps required to put the Union Wire Rope facility on a generator only status.

If you have questions, please contact me at (816) 242-5851.

Very truly yours,

Leland H. Scott RCRA Coordinator

LHS/sk Encl.

cc: Mr. K. A. Niebrugge

Mr. D. E. Allison

Mr. H. E. McCune, Middletown

Mr. R. L. Bernens,